



Picture 1: broken place



The Broken internal and external plate should be integrate to the production of each FRL board. They will be taken out when all components will be soldered on the board.

The Broken places are shown by arrow and should looks like picture 1.